Milton SLS
Safety checklist

Safety Procedures:

1) Always wear your safety glasses when working on the equipment and in the lab.
2) Make sure when soldering not to get burned and use the proper soldering iron procedures.
3) Use caution when using power tools and equipment.
4) Always clean up after yourself in the lab. Wash hands with cold water if you were soldering
5) Electrical Wiring should be neat and of workshipman like quality.
6) Always make sure your ROV is plugged into the GFI outlet before plugging it in or putting the ROV into the pool.
7) Always check your wiring on your ROV for loose or exposed wires.
8) Covers should always be over the propellers.
9) Physical Inspection to see if things are going to fall off of the ROV.
10) Looks for Sharp or Hazardous objects that could cause injury.
11) Make sure the tether is secure on both ends of the control box and the ROV.