Job Step

Potential Hazards	Recommended Risk Control Measures	Responsible Person	Initial
Electrical Shock	Inspect ROV's electrical components for damage		
Electrical Shock	Use water proof connections		
Entanglement	Inspect cable routing. Keep wires organized		
Loss of Visibility and Navigation	Maintain shore communications. Inspect communication systems(ethernet etc…)		